

Date:	No:	Page:
01.03.2019	TB2019-03	1 of 1

Applies to:		Bulletin subject:
WTD	X	IMS bridge control system with 2 nd generation PC system
SAFETY WINDOWS		
AUTOMATION	X	
Created by:		GDA
Approved by:		OOR

End of life notification:

IMS Technologies is not able to support new computers for vessels sailing with 2nd generation PC system. If one of the two bridge computers is failing, the controlsystem have to be upgraded to the lastest technology.

For vessels having V3 controlcards, only the bridge control system is required upgraded. For vessels with older controlcards newer generation controlcards are in addition required. Please see IMS Technical bulletin [TB2019-01](#) for futher information of controlcards.



Picture 1 Typical 2nd generation PC system



Picture 2 Typical Bridge Mimic for 2nd generation PC system

The IMS 2nd generation PC system was delivered in period 2001-2011. Please contact IMS LCS if you are in doupt of what system is installed on your vessel.

Lead time for new control system is 12 weeks.

Please contact: service@imstec.no for further information.